



Performance to the Core

thermo**PLY**[®]
structural sheathing by **OX**

GREEN, RED, BLUE, & AMG

OX Engineered Products

22260 Haggerty Road Suit 365

Northville, MI 48167

p. 248.289.9950

f. 248.289.9955

oxengineeredproducts.com

Damage Repair Guidelines

Damage to Panel Description	Repair Guideline
Facer Delaminations	Small Areas: Sheathing Tape (2-7/8-inch Ox Sheathing or equivalent.) Large Areas: Liquid House Wrap (StoGuard or equal)
Tears or holes in Thermo-Ply less than 1" in length or diameter (non-structural)	4" Self-Adhering Flashing Tape meeting AMMA 711-07 (Ox Arctic Flash Flashing Tape, Titan Butyl Flashing or equivalent)
Tears or holes greater than 3" up to 8 inches in diameter	Blocking can be min 2x4, above and below damage and apply Self-Adhering Flashing Tape meeting AMMA 711-07 (Arctic Flash Flashing Tape, Titan Butyl Flashing or equal)
Tears or holes greater than 8"	Block behind the tear or hole, fasten with proper fasteners, and apply flashing tape over the hole/ tear and fasteners

**These guidelines should be used with good judgement to ensure sheathing maintains intended structural, moisture, and air barrier requirements.*

***Utility or trade (deliberate penetrations) are not considered damage.
Please refer to penetration treatment above.*

AMRIZE

OX Engineered Products is part of the Amrize family of brands